#### ST THOMAS, ONTARIO

August 24, 1906

Eight o'clock on the morning of August 24<sup>th</sup> 1906 the Canadian Pacific morning train to Toronto, with small CPR engine 309 was leaving the massive Michigan Central station that it shared in downtown St Thomas. The CPR swings west and north out of St Thomas. Near the city limits, the CPR train started heading more north; then it would cross the joint CNR-Wabash railway on a semaphore protected diamond crossing. The CPR regular passenger train had the right of way.

This same morning at the same time the Wabash Railroad had an eastbound "Opera Special" of five cars running from Chicago to New York City. The locomotive was Wabash No. 1885, a 2-6-0 Mogul. Just after eight o'clock it left the Wabash station crossed the Pere Marquette-L&PS diamond and built up steam. It would have only one stop for water at Cayuga. Ahead the engineer thought that there was a clear crossing on the semaphore at the CPR diamond crossing one mile from St Thomas.

At 8:15 the two engines smashed into each other, the Wabash struck the CPR locomotive cab at just a slight angle right on the diamond crossing and were thrown in the ditch.

Canadian Pacific engineer John McKay was killed in the collision, but about two hundred passengers escaped injury.

The Evening Record, Windsor, Ontario The Evening Journal, St Thomas, Ontario The Globe, Toronto, Ontario

#### BELLE RIVER, ONTARIO

February 21, 1907

Quite a serious rear end collision occurred about two miles west of Belle River on February 20<sup>th</sup>, 1907 at about four o'clock that afternoon when Wabash passenger train No. 3 crashed into the rear end of another Wabash passenger train.. The engine and the passenger car were damaged in the collision.

#### CANFIELD JUNCTION

March 5, 1907

The Wabash passenger express No. 8 running Detroit to Buffalo ran into an open switch during the night of March 5<sup>th</sup>, 1907 at canfield Junction. The engine and two cars of horses were upset in the ditch. The fireman was injured. A train from Toronto was on an adjoining track. Had the Wabash locomotive derailed on the other side into that train the injuries would have been much higher.

#### SIMCOE

July 27, 1907

Wabash locomotive No. 1894 was running on the fast freight No. 82, Detroit to Niagara Falls, over the Wabash route west-bound; when at around 6:50 on the evening of July 26th, 1907 it stopped at Simcoe for water. It then started up and shortly, only over a mile from the Simcoe station engine 1894 blew up. A boiler explosion! Front brakeman Louis Norton was riding in the cab with Engineer Dennis Patterson and Fireman Fred Calvert. The force of the explosion was described as terrific and engineer Patterson was literally blown to pieces. Brakeman Norton was fearfully scalded and inhaled so much steam that he died shortly after the explosion. Two freight cars were blown off the track and soon erupted into fire.

# ENGINE EXPLODED, TWO TRAINMEN DEAD

## Engineer Patterson and Brakeman Norton Met Terrible End in Unexplained Accident on Wabash at Simcoe—Fireman Probably Fatally Injured.

1407

St. Thomas, July 27.—Engineer Dennis Patterson and Front Brakeman Louis Norton, both of this city, are dead, and Fireman Fred Calvert is probably fatally injured as the result of the blowing up of Wabush engine No. 1894 a mile and a quarter east of Simcoe station last night at 6.50 o'clock.

The engine was attached to fast freight No. 82, bound from Detroit to Niagara Fulls, over the Wabash. At Simpoe the train stopped to get water and at the time of the agained was proceeding at a high rate of speed.

Front Brakeman Norton was riding in the cab, together with Engineer Patterson and Fireman Fred Calvert. The force of the explosion was terrific and Engineer Patterson was hterally blown to bits.

Brakeman Norton was fearfully scalded and inhaled so much steam that he died, shortly after being

brought to Amasa Wood hospital. Fireman Fred Calvert is in a very critical condition, having both legs broken and being badly shaken up. Besides this he is severely scalded and it is feared that he also inhaled considerable steam.

Two cars were blown off the track, which was demolished for many yards.

Both cars took fire and were totally destroyed. The line was blocked all night in spite of the hard work of the crew of the wrecker.

Brakeman Norten was the son of Mr. and Mrs. James Norton, New Scrum, and is survived by five brothers and one sister, David and Henry, of New Sarum; James W., Jacob and Earl, of St. Thomas, and Mrs. H. J. Mills, of Yarmouth Centre. He is also survived by his widow.

Engineer Patterson had only been married three weeks and the trip was the third one he had nade. His body was taken to Simeoe.

WINDSOR EVENING RECORD

July 27, 1907

### TILLSONBURG, ONTARIO

January 2, 1908

A Wabash freight train from the east had two double-headed steam locomotives on the front to pull its heavy train on the early morning of January 2<sup>nd</sup>, 1908. Even with two engines the train was too heavy, so it was decided to split the train for the uphill grade. The first part was taken up the hill to Corinth. The two engines were now backing down the grade to pick up the rear of its train that had been left in a siding. The Grand Trunk Railway also ran a fast freight over this line, train No. 93 and it was the GTR fast freight from the east came bounding along. The two trains collided at the east end of the long viaduct west of Tillsonburg. The wreck occurred at three o'clock on this winter morning. Grand Trunk Engineer John J. Walker was killed instantly. The fireman, J. Bush jumped from the engine in time. The Brakeman, J McCray lost his leg due to the collision. The Wabash locomotives were backing down and it was the tender that received the impact.

## NIXON, ONTARIO

February 9, 1908

A west-bound Wabash express train struck a broken rail between Nixon and Delhi at around eleven o'clock on the morning of February 9<sup>th</sup>, 1908. The entire train that consisted of one coach, three sleeping cars and a baggage car were all derailed. Two of the Pullman sleeping cars rolled down the embankment. Fifty passengers were on board the train. Only seven persons were slightly injured.

## STEVENSVILLE, ONTARIO

June 9, 1908

On the morning of June 9<sup>th</sup>, 1908, at five o'clock the Wabash train No. 1, from Chicago to New York met with an accident near Stevensville, just west of Fort Erie. While travelling at a mile a minute, through some defect in the locomotive tender the tender derailed It was just a mile west of Stevensville and between two culverts. Four passenger coaches jumped the track. Many passengers were injured but there were no fatalities. The engine and the parlour cars remained upright on the embankment.

### Adventures on the Air Line.

Being Those of Bro. Thomas A. Duff, Agent of the Orange Autual.

On the morning of the 16th Bro. Dick drove me up to Tillsonburg to take train for Moulton, which is located between Canfield Junction and Fort Erie. The only train that stops between Canfield and Weiland
Junction is No 72 on the Grand
Trunk, and it is a "mixed" It is
due to leave Tillsonburg at 8.50 a. m. but did not get away until 10. Of all the delays I ever experienced, this was the "king pin." The despatchers delinerately held this train up at every station without apparent reason or necessity, the only object being to give right-of-way to Wabash freight trains of American cars. To give one illustration, we arrived at Darvis about 1.05 p.m., and by 1.30 all work was done and No. 72 ready to leave, but orders were issued to meet two freights there. We lay on the side track until after 6.15, when the previous order was armulled and we were ordered to cross at Cayuga, some 15 miles further on.

Another illustration: A commercial traveler got on the train at Courtland. He got off at Simcoe. went up town saw his customers and caught this train before it left the station. He then went on to Jarvis. went up town, wrote three orders, and was back in time to catch Wabash No. 2 and go as far as Cayuga, getting his besiness done there, and there boarding our train again. The conductor and train hands were very courtrous and kind Besides myself. there was a young lady and a little girl bound for Moulton, and the train hands offered to share their field with 28 No 72 is due in Moulton at 2 30, but did not arrive until 10 p. m., occupying exactly hours to run ... miles,or at the rate of 51 miles per hour Although there are many passenger trains running east between Canneld and Welland Junction this No. 72 is the only one that stops and where between the two places. The Grand Trunk has been declared "for the general advantage of Canada," and received large sums by way of municipal bonus and Government aid but today it appears to be run for the general advantage of the Grand Trunk, and a preference for American freight and passengers (at 2c a mile), to the detriment of Canadian freight and passengers (at se per mile). It is felt that at least one passencer train per day should make the round trip over this road hetween Canfield Junction and Fort Frie, and serve the towns on the line. The above state of affairs is said to be of daily occurrence, and the day before, this same train, due at Moulton at 2.30 p.m., did not arrive until 3 a m. from 6 a. m. Thursday entil 8.30 a.m. Friday is too long for even "yours truly" to go without a rical. The manner is which this train is regularly used and run should be brought to the attention of the Railway Commission, and the Grand Frunk compelled to give Canadian passengers as fair a show at least as they give to American freight.

...

## ST THOMAS, ONTARIO

March 14, 1909

The eastbound Wabash Continental Limited dashed through an open switch in the Wabash St Thomas yards and smashed headon into a standing westbound Wabash freight train. Engineer Blanning on the express saw in time the open switch and quickly applied the emergency brake. Engineer Blanning and his fireman William Chater both had time to jump, unfortunately on the freight, engineer Thomas Arnum and his fireman, Thomas Cade had little warning and were caught falling between the locomotive and the tender. They were somewhat scalded.

## February 8, 1910

Freight train stalled it is necessary to detour passenger trains. There was a big snow storm near the line of the Wabash east of Canfield Junction on Monday night and Tuesday morning. Snow was drifting onto the tracks in such large quantities that a freight train was stalled for some time. This necessitating the detour of Wabash train No. 1 express over the Grand Trunk from Fort Erie via Port Colborne to Canfield Junction. The accommodation train was running three hours late.

March 8, 1910

Thames river Flood. Prairie Siding experiencing the worst flooding in a great many years. The railroad has to work to save its tracks. Trains are under slow orders. At Prairie Siding the whole village is submerged. All trains whether east or west bound since yesterday morning have been running on the eastbound (southern) track, the westbound (northern) track being reserved for the ballast trains running between Prairie Siding and Chatham.

March 9, 1910

The Wabash are using dynamite to break the ice jam.

March 10, 1910

Dynamite is of little use, for there are thirty square miles flooded.

March 11, 1910

Ice jam breaks and the flood and ice crisis is over. Over 200 carloads of cinders had been rushed to Prairie Siding to contain the water.

April 25, 1910

Finest train ever seen here with a Wabash special train with Buffalonians en route to London stops in St Thomas overnight. It was a special Pullman train carrying 150 people.

May 11, 1910

A unique motor car driven by gasoline passed over the Wabash railroad. The arrival of the cigar shaped gasoline motor car at the Wabash station on Wednesday afternoon attracted quite a large crowd. It was manufactured by the McKeen Motor Car Company of Omaha, Nebraska and was en route to Buffalo where it will be delivered to the Buffalo, Rochester and Pittsburg Railway. It is for interurban service. It is fifty-five feet long with distinctive round windows and seats seventy-five people.

May 19, 1910

The future of the Wabash. The Rock Island appears to be after the Wabash and another report states that the Canadian Pacific is interested.

June 20, 1910

A grade crossing accident at Aylmer involving engine No. 1630.

June 25, 1910

Another grade crossing accident near Tillsonburg involving engine No. 1630 and engineer William Sanderson.

July 19, 1910

Wabash men out on strike.

July 23, 1910

Wabash men back to work.

September 9, 1910

Wabash train caught fire. The Continental Limited on the Wabash Railroad which left Windsor at 10:58 Wednesday night was in danger of destruction by fire when a spark from the engine ignited the vestibule of one of the coaches. The blaze was discovered a short distance out of Windsor and was smothered, but fire broke out again, and again. Four stops were necessary.

November 4, 1910

CORINTH, ONTARIO

Wabash Engineer George Smith was killed on the Friday evening at Corinth, Ontario in a head-on collision. He was the engineer of an eastbound freight train drawn by engine No. 1901. His fireman was George booze, and the Conductor was Cyrus Wadham. The westbound train was drawn by engine No. 1807, in charge of Engineer W. Lowie. The wreck occurred at 7:53 as the westbound was in the process of taking the siding at Corinth when the eastbound came along at a good rate of speed and crashed into the westbound, striking it at the eighth car ahead of the caboose. Engine No. 1901 was thrown over onto its side crushing Engineer Smith.

December 8, 1910

NEW SARUM, ONTARIO

Engine No. 1892 was running light drawing just a caboose and it was under the charge of Engineer N. J. Curran. They had orders to take the siding at New Sarum to let and eastbound train pulled by engine 1894, Engineer Joseph Grice pass. The eastbound, engine 1894 reached the station first, and when the westbound came along it was standing just to the west of the switch. Engineer Curran was making every effort to stop the train. The rails were wet and his engine had become disabled on one side that prevented him in stopping engine No. 1892. Engine No. 1892 went over the switch and crashed into the other engine. All the engine crews escaped uninjured.

### January 13, 1911

A small wreck occurred at the Grand Trunk depot at Welland on Wednesday morning April 11, 1911 when a Wabash engine with a caboose southbound smashed into a freight train standing at the depot partly wrecking the Grand Trunk caboose and crushing the front of a freight car. The locomotive was badly damaged, the front trucks being torn off the tracks. The engineer was slightly injured but the rest of the crew were unhurt. A bad curve in the road badly obstructed the view. It was claimed that the semaphore was down.

### February 7, 1911

The wrecking of five cars on a Wabash train at Baird's Crossing west of St Thomas on Tuesday morning at seven o'clock. The cause was a broken rail. Nobody was injured.

## February 23, 1911

Girls given a fast ride. Wabash passenger train No. 2, with engine No. 1837, in charge of Engineer McGregor was forty minutes late when it pulled out of St Thomas on Monday, but made up time between the St Thomas and Buffalo. The train carried the lady winners of the Chatham News and the Windsor Record popularity contests and had to come to Buffalo in order to make connections for Florida.

### March 6, 1911

The engine and five cars of an eastbound Wabash freight. In charge of engineer John Taylor and Conductor McNichol went off the track on the derail at Canfield Junction.

April 10, 1911

Ernest Wilson the Grand Trunk station agent at Belle River was killed when he stepped in front of Wabash light engine No. 1901, westbound and running at forty miles an hour.

May 1, 1911

The engine and six cars of the westbound Grand Trunk-Wabash way freight were derailed between Middlemus and Ekfrid Saturday morning by the dropping of a brake beam. No one was injured. Engineer Little and Conductor Burns were in charge of the local.

### July 24, 1911

A bad smash up occurred about eleven o'clock Saturday night at the Grand Trunk station, Cayuga when eight cars were derailed and badly smashed. The train was heavily loaded with merchandise and a car of chickens. There was an attendant sleeping in the chicken car. The car had left the rails Traveled over the Grand River bridge and then tumbled into ditch when it hit the switch by the station. A coping stone on the bridge was dislocated.

### October 27, 1911

A small derailment at Renton forced the Wabash to detour No. 2 passenger train over the Michigan Central between St Thomas and Canfield Junction. No. 2 pulled by engine No. 1872, in charge of Engineer Charles Knight and Fireman Richard Rolling was on its way to the Michigan Central, using the Pere Marquette-L&PS line between the two stations to make the connection. However just as the big locomotive was about to take the curve at the Dake House she left the rails and after tearing up the track, rails and ties for a distance of fifty feet came to a stop in the ditch to the west of the wye. The derailment was no doubt due to the fact that the rails on this part of the line are too light for a heavy engine. The engine crew stuck to their posts and were uninjured.

## December 11, 1911

A derailment of Wabash engine No. 1622, a baggage car, a smoking coach and part of a sleeping car on train No.1, occurred at the Simcoe station when an axle broke on engine No. 1622. Engineer Britt immediately stopped the train and there were no injuries.

## LOCOMOTIVE EXPLODES; ENGINEER CADE) KILLED

Large Mogul on Grand Trunk Blows up at Thamesville— Engineer Thomas Cade, Fatally Injured, Dies Later in in St. Thomas Hospital.

St. Thomas, Dec. 80.—Engineer Thomas Cade, injured in a locomotive explosion at Thamesville last night, died at nine o'clock this morning at the hospital here.

(Star News Service.)

I hamesville, Dec. 30.—Mogul locomotive No. 1890 on a west-bound Wabash freight, exploded last night opposite the Grand Trunk station nere about tweive o'clock. The explosion was so terrific that the whole town was awakened from alamber.

Engineer Cade of Windsor was blown out of the cab window and fatally injured, his head and arms being terribly scalded. Fireman Cook was blown cver the top of several cars but miraculary

ously escaped serious hurt.

When the explosion occurred the whole body of the engine was lifted almost clear of the trucks and turned completely over. Parts of the cab were picked up rods away.

Engineer Cade was put aboard Wabash train No. 4 and rushed to the St. Thomas hospital. It is thought he will

die.

Engineer Thomas Cade referred to is with light mjuries.

a cousin of Frank Cade, the Windsor patrolman, it although well known to many here is at Inwood, Ont. near St. 2. as, not Windsor, as has been report

According to men prominent in local railway arcles the unfortunate engineer hid repeatedly complained to the officials that the engine was unfit for sevice and that he was endangering his life by delving it. He was told, however, that he was to get all the use possible out of the "load of junk" and to run her the limit.

Reports from St. Thomas. the injured man was taken, that the exposion was caused by the water in the engine running low and cold water eing turned on which struck the soiler. This is denied by Edward Cok, Goyeau street, was brakeran on the train. had just swing off the engine, which was still in motion, to run to the station for orers when, without a minute's warning, the explosion came. Cook was thrown some against the side of the station. Fireman Ball, & St. Thomas, was thrown a distance of 200 feet, but escaped

WINDSOR Evening Record December 30, 1911

## LOCOMOTIVE EXPLODES: ENGINEER CADE KILL

Large Mogul on Grand Trunk Blows up at Thamesville-Engineer Thomas Cade, Fatally Injured, Dies Later in Dec 30 in St. Thomas Hospital.

St. Thomas, Dec. 80.—Engineer Thomas Cade, injured in a locomotive explosion at Thamesville last night, died at nine o'clock this morning at the hospital here.

. (Star News Service.)

hamesville, Dec. 30.-Mogul locomotive No. 1890 on a west-bound Wabash freight, exploded last night opposite the Grand Trunk station nere about tweive o'clock. The explosion was so terrific that the whole town was awakened from slumber.

Engineer Cade of Windsor was blown out of the cab window and fatally injured, his head and arms being terribly scalded. Fireman Cook was blown cver the top of several cars but miracul-

ously escaped serious hurt.

When the explosion occurred the whole body of the engine was lifted almost clear of the trucks and turned completely over. Parts of the cab were picked up rods away.

Engineer Cade was put aboard Wabash train No. 4 and rushed to the St Thomas hospital. It is thought he will

die.

Engineer Thomas Cade referred to is with light njuries.

a cousin of Frank Cade, the Windsor patrolman, it although well known to many help in home is at Inwood, Ont. near St. 2 as, not Windsor, as has

According to men prominent in lo-cal railway arcles the unfortunate engineer hid reneatedly complained to the officials that the engine was unfit for service and that he was endangering his life by deiving it. He was told, however, that he was to get all the use possible out of the "load of junk" and to run her the limit.

Reports from St. Thomas. the injured man was taken, that the exposion was caused by the water in the engine running low and cold water being turned on which struck the loiler. This is denied by Edward Cook, Goyeau street, was brakeran on the train. had just swing off the engine, which was still in motion, to run to the station for orers when, without a minute's warning, the explosion came. Cook was thrown some against the side of the station. Fireman Ball, & St. Thomas, was thrown a distance of 200 feet, but escaped



January 10

TEMPERATURE - ABOYE.

ST. THOMAS,

## N SHEET WAS BURNED, BUT TER GAUGE WAS CLOGGED

Evidence at Inquest Over Explosion of Boiler on Wabash Engine at Thamesville Also Shows That Locomotive Was Not in Good Working Order; Another Adjournment

The inquest into the death of Thomas staybolts, and that there was a defect Edward Cade of St. Thomas, Wabash rallway engineer, who died in the Amasa Wood Hospital on Dec. 30, from injuries caused by the bursting of his engine, No. 1800, at Thunesville, the same day, was resumed at the City Hall Monday night before Coroner Guest and jury, comprising P. L. M. Egan, foreman; C. Riddle, D. J. Lumley, W. E. Cook, John L. Coutts, Peter Brown, W. Kimball and T. C. Mallory.

The inquest was conducted in the

The inquest was conducted in the police court, which was packed with railway men all more or less interested in the dry technical terms descriptive of the various parts of the engine involved in the accident.

About eleven witnesses were heard before the court was adjourned until Tuesday afternoon, when the jury will visit the Wabash yards to view the remains of 1890 and then adjourn again till 7:30 p.m., on Thursday, when it is hoped that John Ball, the deceased en-gineer's fireman, will be able to be present. 

Water Glass Clogged.

The evidence, though intensely techmical; was not without its thrills, as when J. N. Robertson, general foreman of the Wabash-G.T.R. locomotive and car department, St. Thomas, admitted that engine 1890 was with drawn from international service on Dec. 21, 1911, because of seven-broken

in the left cylinder saddle of which he knew and that a message was received from Lawrence Station, signed by Enginer Cade and Conductor Cudmore, complaining that the engine was notmaking steam good. And again when Frederick G. Mitchell of London, who inspected the wrecked engine for the Crown, stated it as his opinion that the lower gage glass connection of engine 1890 was clogged 75 per cent of its size and that the accident was in all likelihood caused by this clogged con-nection being stopped by a small particle of foreign matter, so retaining water in the glass and misleading the engineer as to the real quantity of water in the boiler, and resulting in the burning of the crown sheet, which caused: the, explosion,

Crown Attorney McCrimmon conducted the enquiry for the Crown; E. Rose of Toronto appeared for the Wabash Company, and R. H. McConnell watched the case in the interests of

Mrs. T. E. Cade, the widow.
In opening the case, Coroner Guest explained that owing to the intensely technical character of the evidence and the seriousness of the circumstances, the inquest would be a prolonged one and would likely necessitate one or more adjournments. He read a medical certificate stating that John Ball, the injured fireman, was not

## SPECIAL CAR TO CONVEY THE BODY

Remains of the Late Thomas E. Cade, Wabash Engineer, Are Taken to Alvinston for Burial

Rhe remains of Thomas E. Cade, Wabash engineer, killed in the boiler explosion at Thamestille, were taken to Alvinston in a special car attached to No. 3 Wabash express on Tuesday. Services were conducted at the family tesidence, 87 Flora street, by Rv. D. Rogers and the Masothe remains by F. M. Bond, W.M., and L. Shiter, chaptain.

The pullbearers were: T. Arnum, J. Potts, G. Luidlaw, A. Else, W. Smith and W. Armstrong, J. H. Dong and C. W. J. Smith were the floral befrees.

The floral fributes included a pillow from St. Thomas Ludge, No. 44, A. E.

the floral tributes included a pillow from St. Thomas Lodge, No. 44, A. F. & A. M., a wreath from B. of L. F. & E. division. Windsor, and a wreath from Charity Lodge, B. of L. F. & E. St. Thomas.

Thomas.

Relatives accompanying the repeals wee: Mr. and Mrs. George Cade, father and mother, of Inwood: William Cade, Learnington: Robert Cade, Sr. and Frank and Edward Cade, Windsor: Mr. and Mrs. R. Small, Komoka: Mrs. Bonk, Windsor: Mr. and Mrs. A. Barber, Westminster: Mr. and Mrs. A. Burber, Westminster: Mrs. A. Munro and Mrs. Andrew Manro of Inword.

1911

condition to appear to give evifor a day or two. e first witness called was Howard rson of Springfield, Ill., draughtsin the motive power department to Wabash Railway. He said the ked engine was built in 1904. In of the Mogul type, of which the pany had 37 in service.

General Foreman Testifies.

N. Robertson, general foreman of Wabash, locomotive and gar departt at St. Thomas, did not know n engine 1896 was commissioned service. He had had thirty years rience. It was the joint duties of self and the locomotive foreman, O'Neil, to examine the engines, and O'Neil, to examine the engines, and o Men, to examine the engines, and made a test of 1890 on Dec. 29 beshe went out. They went up and the tracks on her for about two The test showed a crack in the e. The test showed a crack in the cylinder saddle. He had the engine d up so that they might determine at to do with her. He worked her ler full pressure of steam. The pops at off all right. The water guage at off all right. The water guage is was working all right. The detrient in the cylinder saddle could not be caused the accident. He did not the gauge cocks. It was possible the gauge cocks. the gauge cocks. It was possible the gauge glass connections to be the gauge glass connections to be gged, but he saw no signs of any struction. The glass worked mit. It There was half a glass of water on he tested the engine. Had eximed the gauge glass mountings ce the accident and they were persetly clear. It was not possible if the auntings were clear for the water

and judge there would be about the soft water encories shes of water covering crown sheet that time. Due to Lack of Water He Says.

ountings were clear for the water use not to werk. The half glass of iss not to werk. The half glass iter would indicate that there are covering the crown sheet.

Witness was kith Mr Al chell when witness was hith Mr Mi chell when I made the examination for the own and showed and time damage me to the fire-box and Jone. They are inside the fire-box. He did not sow him the gauge cocks, but saw mi look at them in the riore room he cause of the explosion was lack of the on the crown theet.

ne cause of the explosion was lack of a cor on the crown theet.

To Mr. Rose. The accident was not ue to any fault in the engine, but to tek of water on the crown sheet. It as the engineer's duty to keep track f amount of water in the boiler by t amount of water in the bolter by leans of gauge cocks and water glass. It should try both frequently.

To Mit McConnell—He examined

ngine 1899 pertendarly because of the track in the cylinder saddle and found to other defect. The engine was in ervice when he came to St. Thomas, twas not in international service at the time of seeddent, it was withdrawn her that service on the 21 because of he time of geoldent, it was withdrawn rom that service on Dec. 21 because of seven broken staybetts in side and hreat sheets and not because of any other defect. It would not pass the requirements of the international service with seven broken staybolts.

Engineer Sent Message.

knew a message was received trom Lawrence Station complaining that the entine was not straining freely, but knew of no other message. No message was sent in reply, to witness'

knowledge.
In reply to further questioning by
Mr. Rose, Mr. Robertson said the crown
Mr. Rose, Mr. do with the boiler,
sheet had nothing to do with the boiler. Sheet had nothing to do with the boiler. The stayholts served to support the crown sheet. The crown sheet was directly over the tire and was held to the outer easing sheets by the stayholts. The main force of the explosion was shown by the crown sheet. The bolts. The main force of the was shown by the crown sheet. The was shown by the crown sheet, of the blue appearance. Faused by heat, of the blue appearance that the explosion crown beet showed that the explosion was caused by lack of water in the

To Mr. McConnell There were brok-

on Dec. 29 after Mesers Robertson O'Nell had tested her. He made no O'Nell had tested her the stay personal examination of the

consultation with Mr. Robertson that it was decided 1850 should go to Fort. Wayner None of the booked realized would have abything to do with the accident. He tested the blow with the brakes on. This was equivalent to testing with a lead.

constitution with Mr. Robertson that toward decided 18's should be plonty to take the rain 194. The was equivalent to the case of the plont to take the plonty to take the rain 194. The plant to take the plont to take the plont to take the plonty to take the rain 194. The plant to take the plont to take the plant to take

the glass was working the chains was tested

the lower 10.75
1830 was a letthis condition the
sign matter might
and prevent the
com Reling down
sken of by other
te nothing to do
short their world
mer would have
much harder to connection on cuts minutest pleas of the holes the opening water in the gians. The blow defect witnesses would be with the explosion that the explosion. mean that the en-to work his better make up for the part t chanical name glass was the dition so far as operastation was con

Opening Was Reduced

much harder feets in the million english the

a dangerous con-was in fair con-

rom that service on Dec. 21 because of seven-broken staybolts in side and hreat sheets and not because of any other defect. It would not pass the requirements of the international service with seven broken staybolts.

Engineer Sent Message.

He did not know of Engineer Cade making any complaint when he took the engine out. If require were needed that the lawrence Station complaining that the length of the state of the section of the water in the gauge glass at one by the first water water water water water water water w

was wreter other that water was less or glass wrons.
Witness over less of a 34 among in gauge connections being stopical by foreign matter, but he had known of

3-16 obenings being blocked.

To Mre McConnell—If water, was taken at the Thames river and the injectors were working right that should be plenty to take the rain to Thamesville.

JANUARY 10 1912

## CROWN SHEET BURNED

(Continued from page one)

in fit condition to appear to give evi-

in fit condition to appear to the dense for a day or two.

The first withless called was Howard Anderson of Springfield, Ill., draughtsman in the motive power department of the Wabash Rathway. He said the wrecked engine was built in 1904, in Philadelphia, Pa., for the Wabash, and was of the Mogul type, of which the company had 27 in service.

General Foreman Testifies.

General Foreman Testifies.

J. N. Robertson, general foreman of the Wabash locomotive and car department at St. Thomas, did hot know when engine 1890 was commissioned for Service. He.had. had-thirty years!

for Service. It was the joint duties of himself and the locomotive foreman, Mr. O'Neil, to examine the engines, and they made artest of 1890 on Dec. 29 hefore she went out. They went up and idown the tracks en her for about two the first showed a crack in the left evilinder saddle. He had the engine had abstant a lead.

Engine Fit for Service

Harry E. Berry, aspector of holier work in the Wabash round house said to four days prior to her last trip. On that occasion be made at general constitution of the had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be made at general constitution of the had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days prior to her last trip. On that occasion be had on inspected boiler of 1890 or four days pr

To Mr. McConnell—Witness said therefrown sheet had been reversed by the explosion, being forced from a concave shape to alconyex. The seventh of the explosion of the explosion of the explosion of the engine to be withdrawn from International service, ere located the engine to be withdrawn from International service, two in right and one left side sheet. The international rules require thereas of an engine if it has two adjoining stay botts broken or three broken within a four four diameter, or five broken it the entire botter. Only absence of water on erown sheet was in his opinion the cause of the secident. Boiler inspector Robson Hinds reported the seven broken stay botts.

Mr. McConnell sought to get an admission from witness that because of the new Dominion act covering iocomotive bollers which came Into effect on Jan. I. 1912, entire 1830 was being sene out of the Country not to return but his questions along this line were not allowed as the first that not one was a way to Fort Wayne.

War on Way to Fort Wayne

Was on Way to Fort Wayne

was on Way to Fort Wayne

Witness, however, admitted that the
engine was going to Fort Wayne for
repairs and that because of this the
repairs reported on the book at the
repairs reported on the book at the
end of her last previous trip were
not made in St. Thomas. The engine
arrived in St. Thomas at 9330 p.m.
loc. 28 and Cade was ordered to take
her out at 7330 p.m. on Dec. 29.
Witness took engine 1890 on per 29.
Witness took engine 1890 on test
on Decr. 29 after Messus Robertson-and
on-Nell had tested her. If made no
personal, examination of the stay
bolts.

To Mr. McCrimmon—It was after
consultation with Mr. Robertson that
it was decided 1870 should be to
Fort Wayne. None of the booked repairs would have anything to do with
the brakes on. This was equivalent
to testim with a bad.

Engine Fit for Service

Harry E. Rerry, aspector of holler
work in the Wabash round house said

Anderson of Springfield, Ill., draughts-man in the motive power department of the Wabash Railway. He said the wrecked engine was built in 1904, in Philadelphia. Pa., for the Wabash, and was of the Mogul type, of which company had 37 in service.

#### General Foreman Testifies.

J. N. Robertson, general foreman of the Wabash locomotive and car department at St. Thomas, did not know when engine 1890 was commissioned for service. He had had thinty years experience. It was the joint duties of himself and the locomotive foreman, Mr. O'Neil, to examine the engines, and they made a test of 1890 on Dec. 29 before she went out. They went up and down the tracks on her for about two mile. The test showed a crack in the left cylinder saddle. He had the engine lifted up so that they might determine what to do with her. He worked her Mr. O'Neil, to examine the engines, and they made a test of 1890 on Dec. 29 before she went out. They went up and down the tracks on her for about two mile. The test showed a crack in the left cylinder saddle. He had the engine fired up so that they might determine what to do with her. He worked her under full pressure of steam. The pops went off all right. The water guage glass was working all right. The defect in the cylinder saddle could not whith the do with her, the worked and under full pressure of steam. The pops went off all right. The water gauge glass was working all right. The defect in the cylinder saddle could not have caused the accident. He did not have caused the accident. He did not east the gauge cocks. It was possible for the gauge cocks. It was mouthus showed the engine. Had examined the gauge cocks mouthus since the accident and they were perfectly clear. It was not possible if the mountings were clear for the water glass not to werk. The half glass of water on the explosion was since the accident and they were prefectly clear. It was not possible if the mountings were clear for the water of the explosion was since the accident and they were prefectly clear. It was not possible if the mountings were clear for the water of the explosion was since the accident and they were dear for the water of the explosion was since the accident and they were the accident and they were dear for the water of the explosion was since the accident and they were the accident and they were dear for the water of the explosion was looked. He did not convert the covering crown sheet. The half glass of water of the water of the explosion was sheet at that time.

Due to Lack of Water He Says.

Witness was with Mr Alf chell when the dear the covering crown sheet and covering crown sheet and the form of the lack was howed aim to disable the covering crown sheet and covering crown sheet and the covering crown sheet and covering crown sheet and covering crown sheet and covering crown sheet and covering crown shee

Mainess was with Mr Michell when led made the examination for the Crown and showed aim the dame, and done, the fre-box and done. They were made the fire-box. He did not show him the gauge cocks, but saw him look at them in the grove reem. The cause of the accelerate ways taken. The cause of the explosion was lack of

water on the crown theet.

To Mr. Rose The accident was not due to any fault in the engine, but to one to any tante in the engage, out to hek of water on the crown sheet. It was the engineer's duty to keep track of amount of water in the boiler by means of gauge cocks and water glass.

means of gauge cocks and water glass. He should try both frequently.

To Mit McConnell—He examined engine 1899 particularly because of the crack in the cylinder saddle and found no other defect. The engine was in service when he came to St. Thomas. It was not in international service at the time of Aceldent, it was withdrawn the time of geoldent. It was withdrawn from that service on Dec. 21 because of seven broken staybotts in side and threat sheets and not because of any other defect. It would not pass the requirements of the international service with seven broken-staybotts.

engine was not steaming freely, but knew of no other message. No mes-sage was sent in reply, to witness knowledge.

knowledge.
In reply to further questioning by Mr. Rose, Mr. Robertson said the crown sheet had nothing to do with the boiler. The stayrolfs served to support the crown sheet. The crown sheet was directly over the fire and was held to the outer easing sheets by the staybolts. The main force of the explosion manichant by the crown sheet. The was shown by the crown sheet. The blue appearance, caused by heat, of the crown here showed that the explosion was caused by Lick of water in the To Mr. McConnell There were brok-

her out at 7:30 p m. on Dec. 29. Witness took engine 1890 out for test on Dec. 29 after Messrs Robertson and O'Nell had tested her. He made no O'Nell had tested her. He made no in fir condition to appear to give evion Dec. 29 after Messrs Robertson and
dence-for a day or two.

The first witness called was Howard personal, examination of the stay

bolts.

To Mr. McCrimmon—It was after consultation with Mr. Robertson that it was decided 1850 should go to Fort Wayne—None of the booked—repairs would have anything to do with the accident. He tested the blow with the brakes on. This was equivalent to testing with a load.

Engine Fit for Service

#### Engine Fit for Service

Dr. F. C. Lawrence gave evidence as to inferies to Engineer Cade.

#### Had Been Repaired Often

It had been sho glass was workin engine was tested dency on the part on the gauze glass. Frequent to its of cocks and try co-no matter how we work.

work. He had found th connection on char-cent encrusted and infinitest piece of position matter marks block the opening and prevent the water fraction gives a comment that the explosion except that it would have to work his better make up for the entire part of the chanical part of cauge glass was in a dangerous condition. The best was in fair condition so far as correstation was condition. minutest piece of b dition so far as escrustation was con-

Opening Was Reduced

the lower 111.5

sin matter mecha

seven broken staybetts in side and threat sheets and not because of any other defect. It would not pass the requirements of the international service with seven broken staybolts.

Engineer Sent Message.

He did not know of Engineer Cade making any complaint when he took the engine out. If requires were needed Mr. Cade would have to book them, the knew a message was received from Lawrence Station complaining that the engine was not steaming freely but water in the gauge glass at one by a for such a period of time might indicate to the engineer that somethings wrethe citizer that water was low or glass wron:

Witness meets hoose of a 24 communication gauge connected being stopped by foreign matter, but he had known of

3-16 obenings being blocked.

To Mra McConnell—If water, was taken at the Thames river and the injectors were working right that should be plenty to take the rain to should be plenty to take the rain to

Charles Cudmore, conductor of Engineer Cade's train, said the train took four hours and fifteen minutes to go from Thamesville to St. Thomas. Stops were made at Payne's Mill. Bairds, Lawrence Station, Thames river (for water), Eckford and Thames-ville. They had to Stop at Payle's Mill (a blow strain to make the grade at Bairds switch for steam. At Lawrence Station witness at engineer's request, sent the message rend.

Mr. Cade made no complaint about water. The train had not stoped dead when the explosion occurred. There appeared to be plenty of, water in the tender. Witness rode on the engine from Thames rivering Glencoe and blew out the gauge gliss withe he was on engir, and tried) the try cocks. There was two inches of water in glass at Glencoe.

Plenty of Water on Tender

Plenty of Water on Tender

January 10 1912

Witness of Engine 1990 x a such fine to the such that it is not the such that is not th

Repaired Every Trip.

Referred in Court of the Learning of the last of the semining of the last of the last trip. She had been in service of Wahash six of acventy wars. Had been repaired a good many times was repaired nearly were done on this occasion. There was some work done to her prior to the previous 'rip. He did not examine her after the work was done to her prior to the previous 'rip. He did not examine her after the work was done. There was some work done to her prior to the previous 'rip. He did not examine her after the work was done. There was a had blow tor an emission of an extra amount of steam through an improper channel) between the steam port and the exhaust port of the left explinder saddle casting. Nothing was done to remedy it. The only effect of the blow would be that the engine would lose power. The message read was the natural outcome of this. The blow would have nothing to do with the accident.

Witness examined the engine after the accident, both at Thamesville and St. Thomas and he explained in detail the condition of the crown sheet and the rest were lying in the main all Mr. Robertson's evidence on this point. He added that four of the ten broken holts were attached to the crown sheet and the rest were lying in the bottom of the boiler. No boils were pulled away from the crown sheet and the rest were lying in the lottom of the boiler. No boils were pulled away from the crown sheet and the rest were lying in the lottom of the boiler. No boils were pulled away from the crown sheet and the rest were lying in the lottom of the boiler. No boils were pulled away from the crown sheet and to receive complaints from engineers on the road. A defect might develop on the road. It was then up to the engineer to make temporary repairs, if possible, and get over the road.

Crown Sheet Reversed

To Mr. McConnell—Withers said the crown sheet had been reversed by the explosion, being forced, from a concave shape to a veonyex. The seventher was a superfect of the engine to a veonyex. The seventher was a superfect of the engine to be withdrawn from international service, ere located, four international rules reguling lithdraal of an engine in throat sheet. The international rules reguling lithdraal of an engine if it has two adjoining stay botts broken or three broken within a four foot diameter, or five broken in the entire bolier. Only absence of water on crown sheet was in his opinion the cause of the accident. Boller inspector Roboson Hinds reported the seven broken stay bolts.

Mr. McConnell sought to ger an admission from witness that because of the new Dominion act covering tocomotive bollers which came into effect on Jan. 1912, engine 1890 was being sen, out of the Country not to return but his questions along this line were not allowed as the het had not come into effect at the time of the accident.

Was on Way to Fort Wayne.

Was on Way to Fort Wayne

CROWN SHEET BURNED

(Continued from page one)

(Continued from page of this the provious from page of this the provious from page of the provious from page of the provious from page of the page of the provious from page of the page of the provious from page of the provious from page of the

1912

## JURY INSPECTS ENGINE NO. 1890

And Learn Meaning of Technical Terms
Used in Evidence: Railway Board
Inspector Also Views Wreck

The jury knystigating the cause of Engineer T. E. Cade's death met at the city hall Taesday authernoon and accompanied by Coroner Guest, Crown Attorney McCrimmon, R. H., McConneil, representing Mrs. Cader. Hugh E. Rose of Toronto, General Forenga J. N. Roberts M. Locomolike Forenga R. J. Catin H. Superintendent Bowker and a number of other Wabash officials and railwaymen, were to the Perg Marquette years to inspect the wreeked engine, No. 1890.

The various technical terms used at the heating on Monday night were explained in the jury he connection with the various parts of the engine, est pecial attention, being, paid to the crown sheet, the gauge gass consections, the injectors, the stay-bolts and the cracked cylinder saddle, to which so much, reference was made. The personal examination and courteons explanations given by the practical men will prove of much value to the jurors in arriving at an understanding of the very technical evidence given and in deciding just what the shortage of water in the boiler was due to and where the blame, if any, belongs,

The proper working of the gauge glass, gauge cocks, try cocks, injectors and the methods of blowing and testing these was shown to the jury on board another engine, which had tree respect for the purpose.

A case inspection of the engine was an example by the Dominion Raliway Board's inspector, Mr. Ogilvie, who returned to Ottowa immediately, afterwards

January 10 1912 January 30, 1912

### **AYLMER**

An engine running light with a caboose westbound was in a collision with a couple of freight cars about 400 yards east of the Aylmer station. The Grand Trunk St Thomas to Brantford local had drawn into a siding at the Aylmer station but two cars were not clear of the mainline. When a Wabash engine and caboose swung around the curve at about forty miles per hour they crashed into the two freight cars. The pilot of the engine was smashed and the two freight cars were thrown from the track, and one car and a caboose caught fire and burned.

August 11, 1912

#### **CHATHAM**

Engine No. 1807, a six-wheeler and every car of Wabash passenger train No. 6 ploughed through an open derail at the Canadian Pacific Railway diamond crossing, four miles east of Chatham at 1:30 on the morning of August 11th, 1912. Although every one of the five cars left the rails and the engine and two cars were juggled around a lot, no one was hurt. The Wabash train was travelling at a fair rate of speed with the semaphore set for clear did not relinquish speed, but the crossing watchman confused and believing that a train was approaching on the CPR tracks quickly threw the semaphore clear for the CPR, and set the derail against the Wabash train. The crew stuck to the engine. Engineer George Wilson and his fireman escaped unhurt. They did not jump.

December 14, 1912

#### **NELLES CORNERS**

Two freight trains, the second section of train No. 94, engine 1871 eastbound, and the first section of train No.91, engine 1900 westbound both travelling at about forty miles per hour met on the single track between Jarvis and Cayuga, just west of the little depot of Nelles Corners. The engineers of both trains Henry Harland and James Black saw the approaching headlights quickly set the brakes and leaped from their engines. Both Harland and Black yelled at their firemen to jump. Fireman Saxon heard Black, but fireman Louis Locke did not hear Harland. With the collision Locke was trapped on the engine and died.

The cause of the wreck was due to Harland and his crew having misread the number of the train displayed at Nelles Corners. The crew of train No. 91 had received orders at Welland Junction to pass train No. 72, engine 1874, and also to meet train No. 94 at Nelles Corners. When Engineer Harland reached Nelles Corners he saw the number of a train displayed in the office window and evidently misread it thinking it was displaying No. 94 when in fact its display was for No. 72. Number 72 was sitting in a siding but its lights were not lit, it sat in the darkness.

As far as could be understood had the crews on the westbound train No. 91, Henry Harland and Louis Locke, misread the numbers 1874 on the engine of train No. 72, standing on the siding, for 1871, the engine that was drawing train No. 91, the train they did have orders to meet at Nelles Corners. When they saw what they believed was No. 1871 on the engine at Nelles Corners they did not stop, but kept on, only to crash into the real 1871 and its train two miles further west.

December 16, 1912

#### WALKERVILLE

A String of freight cars left standing on the mainline while the other cars were shunted around caused a wreck on the Wabash Sunday afternoon, at 4:15, just west of the Sandwich Street bridge, at Walkerville. A freight train from St Thomas drawn by two big engines drew slowly under the bridge and collided with the boxcars. One engine was completely turned over and its tender dumped and the other engine was derailed. Most of the engine crews on both engines as they came around the curve saw the standing freight cars and jumped with the exception of the fireman on the first locomotive Alexander Neish, who was badly scalded.

## December 31, 1912

Yesterday, there was a Wabash time change and passenger trains No 103 and No. 6 which formerly went by Niagara Falls now cross at the International Bridge, Fort Erie and run through Welland Junction and all the way over the Air Line. It is said that the change was brought about owing to the small passenger traffic going and coming from Niagara Falls.

Welland Tribune

## September 16, 1912

Four new sidings at St Thomas to store coal. The GTR have within the past week constructed four lines of sidings on the company's property between Inkerman Street and Woodworth Avenu south of the mainline. The tracks are being put into accommodate coal cars. At present St Thomas is the distributing point for the coal chutes at Nixon and Glencoe, as well as St Thomas. The yard capacity has been taxed.

## October 5, 1912

Steam escapes from the boiler. When an axle broke on a Wabash locomotive at Nelles Corners Friday it opened the purge cock and all the steam escaped from the boiler. As a result traffic was tied up for a short time while an engine was sent out from St Thomas.

## October 7, 1912

Wabash express train No. 1 was several hours late on Sunday morning not arriving until 11:30 in the morning. The train was first delayed several hours at Buffalo because the eastern connections were late arriving and then was delayed again when a locomotive attached to a heavy freight train threw a (drive wheel) tire.

## October 29, 1912

Robert Edgar, one of the company's oldest employees and a former engineer was confused by the noise of an engine on one track and walked in front of Wabash engine No. 1837 and was killed.

AND CENTRICK CUPT

## Fireman Louis Locke Killed i Head-On Crash of Freight Trains on Wabash at Nelles Corners

## HAD BEEN MARRIED ONLY FEW MONTHS

Louis Locke, the Walnash fireman killed in the crash near Nelles Cornersearly Saturday morning, is only 27 years of age. He was married only last spring to Miss Mabel Grice, daughter of Joseph Crice, Wahash engineer, Balaclava, street. For a time-after his marriage Mr. Locke was engaged in farming in Yarmouth, but returned to the city two months ago to resume work as irreman, on the Washash; a position he held two years ago. At the time of his death he was residing with his wife at No. 141 Balaclava street.

At the time of his death he was residing with his wife, at No. 141 Balaclavi street? The deceased was a son of the Intervillant Locke of Varinouth, and besides his wife, is survived by his mother, Mrs. John Tabraham, of North Yarmouth; and three sisters and three brothers, viz., Mrs. Job Henderson, city; Mrs. John Sheldriek, Talbotville; William Locke, L. & P. M. Stravel road, Varmouth; Charles Locke, St. Thomas and Wesley Locke. North Yarmouth. The remains will arrive in St. Thomas at 11:40 tonight and will be taken to the undertuking parlors of P. R. Williams & Son, The funeral will be on Tuesday from the home of deceased's father-in-law, Joseph Grice, Balaclava street.

December 1912

THE DEAD FIREMAN! Engineers James Black and Henry Harland and Fireman William Saxon Receive Minor Injuries by Jumping When They See Collision is Unavoidable; Engines and Cars Piled Up and Traffic Blocked for Twelve Hours; Trains Detoured Over M. C. R.

#### MISREADING OF NUMBER IS GIVEN AS THE CAUSE OF THE DISASTER.

#### KILLED

LOUIS LOCKE, fireman, aged 27, married, 141 Balaclava street, St. Thomas.

#### INJURED

JAMES A. BLACK, engineer, 36 Flora street, sprained ankle and

HENRY G. HARLAND, engineer, 18 Hughes street, sprained ankle and

WILLIAM SAXON, fireman, St. Catharine street, shoulder dislocated. WALTER QUEEN, brakeman, St. Thomas, foot scalded and knee in-

Louis Locke, Wabash fireman, residing with his wife at No. 141 Bala-1 clava street, St. Thomas, was instantly killed in a head-on crash on the Wabash, two miles west of Nelles' Corners, shortly before two o'clock Saturday morning.

Three other St. Thomas men. Engineer James A. Black, Engineer Henry Harland and Fireman William Saxon, escaped serious injuries By

Walter Queen, brakenian, was thrown from the cars after the crash and injured.

The wreck was one of the most disastrous in the history of the road. Two freight trains, the second No. 94, east-bound, and the first No. 91, westbound, both traveling at a rate of speed estimated at something like forty miles an hour, met on the single track west of Nelles' Corners, in the dark of the early morning.

#### EIREMEN'S TERRIBLE DEATH

When Engineers Harland and Black on their respective engines saw the headlights on one another's engines, they immediately reversed and, seeing there was no chance of avoiding a smash, yelled to their firemen to jump and cleared for safety themselves.

Fireman Saxon heard the call of Engineer Black, but Fireman Locke apparently did not hear Engineer Harland. When the two huge locomotives crashed together Mr. Locke was caught between the tender and the bollerhead and terribly crushed and scalded. It was some time before his com-rades were able to secure the release of his body.

#### MISTOOK NO. 72 FOR NO. 94

The cause of the wreck, the Wabash officials here say, was due to Engineer Harland and his crew having misread the number of displayed at Nelles' Corners. The crew of this train, No. 91, had received orders at Welland Junction to pass No. 72 and also to meet No. 94 at Neiles' Corners, When Engineer Harland reached Neiles' Corners because the number of a train displayed in the office window and evidently misread it, as he was under the impression it had read No. 44, whereas the agent says the number displayed was 72. It is also said, on behalf of Engineer Harland, who is considered one of the most efficient men on the road, that the failure to display lights on train No. 72, which stood on the siding at Nelles' Corners, had masked him into the being that it was No. 94 and not an extra that he was possing. LINE-BLOCKED TWEEVE HOURS

#### The wrecking creve were rushed to the scene from St. Thomas and Fort Eric, but it was tweive hours before the mass of broken up cars and torn-up tracks were again in Shape for traffic. In all some ten cars were demolished, while the two big engines, locked fast in each other's embrace,

rolled over into the duch! The accident occurred in a deep cut and wear a curve, which prevented the engineers from sceing the danger they were in until the accident was unavoidable

While the work of clearing up the wreckage was in progress passenger trains, two east-hound and three west-bound, were defoured over the M. C. R.

Train No. 54° was in charge of Conductor McAlpine, of St. Thomas, and No. 91 in charge of Combestor Brown, of Windson. The locamotices in the

wreck were No. 1811 on tran No. 94 and Poor en No. 91.
FAJURED MEX AT THEIR HOMES.

The injured men were brought to St. Thomas about nine ofcock and were placed under the care of the company's physician. All were sufferingmore or less train shock and from them beinges and outs, as well as the injuries identified above. After having their injuries attended to all went to, their houses. Brokens in Queen received his injuries by being thrown from the train when the carriers of occurred.

The body of Fireman Locke, which is terribly washed and scaled, is say still held at Nelles' Corners, and an asquest will be held.

#### TWO CENTS PER COPY

## READING A "4" FOR A "1" CAUSE OF ACCIDENT

Coroner's Jury, Investigating Nelles Corners Wreck, Ihinks Train Crew Should Have Stopped to Make Sure

## TRAINS ONLY 50 YARDS APART WHEN FIRST SEEN

Trainmen Tell of Little Time They Had to Make Jump for Their Lives; The Jury Makes a Recommendation

#### THE VERDICT

"We, the jury, find that the train crew on the west-boundtrain were at fault in not stopping and making sure of thenumber of the train they were to pass.

to pass.
"We also think that the railway company should make it specific that all trains should stop to be sure of the train they are to pass."

#### (Staff Correspondence)

Cayuga, Dec. 17.—The above was the verdict rendered by Coroner Snjder's inquest, which was held here Monday afternoon, to enquire into the death of Lewis Locke, Wabash fireman of St. Thomas, killed in a head-on collision two miles west of Nelies' Corners, early Saturday morning.

The evidence of the different members of the train crews showed plainly that none of them were at fault in the performance of their duties, but that it was just a plain case of an epitical illustion or the reading of a figure "4" for a "1."

#### Operator Testifies.

The first witness called by Crown Attorney Murphy was B. H. Bratten, night operator at Welland, who stated that he had given an order to Conductor Arthur Brown of the west-bound, in charge of train first 91, to meet train second 94, engine 1871, at Nelles' Corners.

Mr. Bratten also stated that the agent at Nelles' Corners would not necessarily have to have a copy of the order handed to Conductor Brown at Weland Junction, so that it the later's train should pass Nelles' Corners without meeting the train his yelers called for there would be no worker attached to the operator at Nelles' Corners, but only to the members of the crew themselves

#### Mistock 1871 tor 1871.

Arthur Brown, or Windsor, conductor of west bound train No. 91, we knowledged reserving the order at Welfind Juristane to most train soone 91, win energies 1871 at Nellos toric is activitated 90 at a sensition to 1, much most the voter attacked by the train of the voter attacked to the energy of When pecked by Mr. Many of the voter mesked

#### READING A "4"

#### (Continued from page one.)

the company and the instructions of the management to trust to their eyes in such cases, Mr. Brown's reply was decidedly in the affirmative. Part of the company's rules regarding the passing of trains reads as follows: "Trains must not pass any meeting point without knowing positively that the train or trains are those which has the right-to-track." Mr. Brown, in reply to a question, stated emphatically that he considered looking at the headlight and seeing the number 1871 as plainly as he did on the glass was what he considered being positive.

#### Brakeman Also Saw It.

Walter Queen, head brakeman of the west-bound train still bore the marks of his strenuous experience, walking with a decided limp, owing to a badly sprained and scalded foot. His testimony coincided with Mr. Brown's with regard to seeing file number 1871 on the headlight of the sldetracked train at Nelles' Corners, with the exception that Mr. Queen stated that his vision was slightly obscured by steam spiralling up in front of the headlight. As soon as he saw the number, as he thought, 1871 on the sidetracks engine, Mr. Queen told Engineer Harland, but did not hear his reply.

Duncan Dougall, Windsor rear brakeman of the west-bound train. No. 91, was the next witness, but could add nothing materially new to the story heard from the previous witnesses. At the time of passing Nelles' Corners, Mr. Dougal was not looking out, so could not see the number of the engine, but did see that there was a freight train on the siding.

#### Headlight Was Dim.

Wm. Saxon, St. Thomas, fireman on the ill-fated east-bound freight, threw some light on the subject from the opposite side of the encounter. Mr. Saxon gave as one reason of the disaster that the headlight on engine 1900, attached to, the west-bound Treight was dim, so dim, in fact, that the green classification lights showed almost as bright as it did. When he first noticed the onrushing engine it was only about four car lengths distant, giving him just enough rime to jump for his life before they crashed together. Under normal conditions, according to Mr. Saxon, the headlight of 1900 should have been noticed fully one half a mile distant, in which case a collision could have been averted.

#### Little Time to Jump.

Frank Marshall, head brakeman on the east-bound freight, was lighting a lantern up until a few moments before the fatal crosh and did not see the oncoming freight until it was perhaps fifty years distant or about the same time that Fireman Savon first became aware of the imminent danker.

ger.
The two engineers, James Brack and Henry Harland, were unable to attend, owing to their injuries.
Transmaster J. A. McLardy of this

Trainmester J. A. McLardy of the feity, and T. P. Gult, of the Hugh Rose

## RS |

law firm, Toronto, Wabash solicitors, were on hand to look after the interests of the company.

December 17

## FIREMAN LOCKE'S HEROIC DEATH

## While His Legs Were Being Slowly Roasted Off in a Red-Hot Vice He Conversed With His Rescuers Dec 16 1912

Despite this he remained conscious and Fireman Locke was an difference to converse with the men who were striving to release him. He lived for an hour after-being-taken out. His right leg was completely burned off at the ankle, while his left leg was burned almost to a cinder. The nen who were aiding in releasing his ody all speak in the highest praise of the pluck shown by Mr. Locke as of the pluck shown by Mr. Locke as ie was held fast and was being slowly roasted and scalded to death.

The remains of Louis Locke, the death is being held at Nelles' Corners unfortunate Wabash fireman, killed in the wreck at Nelles' Corners, Saturday evening and were taken to the undertaking parlors of P. R. Williams & Son. The funeral will take place from his late residence, 141 Balaclava street, at 2:30 o'clock on Tuesday.

Fireman Locke met a terrible death. When the crash came he was caught by the lower part of his legs between the boilerhead and the tender and held fast there for four hours, despite the efforts of his comrades to release him. During all this time his legs were held fast against the hot metal of the boilerhead. Other parts of his body were being scorched by the escaping steam, and his head hung over the top of the boiler. Despite this he remained conscious a greater part of the time and was a greater part of the time and was

and Fireman Locke was on the gang

#### These Cold Winter Vights

When 1874 Looked Like 1871. he will enjoy those Tref sigure you. The inquest into Fireman Locke's In special boxes of 25 on the St. No. 1885.

ONTARIO, SATURDAY, AUGUST 31, 1912.

SUNDAY-FAIR AND WARMER.

## Wabash Train Left Rails at Derail Near Chatham

Engine and Five Cars All Off, But Injuries to Passengers Are Only Trifling, While Train is Able to Proceed After Few Hours Delay; Confusion of Signals the Cause

The engine and every car of Wabash | passenger train No. 6 ploughed through an open derail at the C. P. R. diamond crossing, four miles west of Chatham, at 1.30 o'clock this morning, and although every one of the five cars left the rails and the engine and two cars were juggled around a lot, no one was hurt, excepting three passengers, who were slightly injured.

The escape was a most miraculous one. The train was travelling at a fair rate of speed with the semaphore set for clear, but the watchman at the crossing, believing that a train was approaching on the C. P. R. tracks, threw the line clear and the derail on the Wabash was thrown open. The signals in the tower, it is said, confused the operator.

Crew Stuck to Engine.

Engineer Geo. H. Wilson of St. Thomas and his fireman escaped unhurt. They did not jump, but remain- | happened.

ed with the engine, which luckily remained upright. None of the passengers were hurt severely enough to require removal to a hospital.

Actress Was Injured.

A vaudeville acrtess, named Snell, fainted and claimed to have had her back and ankle hurt, but she was able to continue to Buffalo with her party. There were in all about a hundred passengers aboard.

One Pullman passenger slept through until seven o'clock this morning, and was surprised to discover there had

been a wreck.

The wrecking crew from St. Thomas, accompanied by the officials, went to the scene of the wreck and soon had the cars all back on the rails, and with a new engine these were in shaps to continue the trip. The train passed continue the trip. The train passed through St. Thomas at 10.15. The tender of the derailed locomotive was crosswise on the tracks, but this was righted at 10.10 o'clock, when traffic was resumed as though nothing had